

TUSB3410/TUSB5052 Virtual COM Port Driver Installation and Uninstallation

This document contains the installation and uninstallation procedure of the TUSB3410/TUSB5052 Virtual COM port driver Windows 2000.

The dialog boxes that are shown in this document indicate what will be seen when installing a TUSB3410UART EVM that has no EEPROM loaded in socket U5.

Driver Installation

OS: Windows 2000

STEP 1. To install the driver, run setup.exe located at the directory \DISK1 on the installation media. This will install all the necessary files in the default directory C:\Program Files\Texas Instruments. The progress is shown by the following windows.




Figure 1 - Driver Installation Process




Figure 2 - License agreement

Although the drivers have not been certified by Microsoft WHQL, TI testing has shown that they pass the HCT test suite used by the WHQL labs. TI plans to obtain official certification in 2Q2005. Contact TI for the latest information.

Because the drivers are not yet certified, the software installation warnings shown in Figure 3 and Figure 4 are generated. The reason two warnings are generated is that the driver is composed of two separate modules, one for the USB functionality and one for the serial port. Choose "Continue Anyway" to install the drivers.



Figure 3 - Installation Warning (first of two warnings)




Figure 4 - Installation Warning (second of two warnings)

Click “Finish” as shown in Figure 5 to complete pre -installa tion of the drivers.




Figure 5 - Pre - installation of drivers complete

STEP 2. Connect the USB -to-serial hardware to the PC. Windows displays the Found New Hardware dialog box (“TUSB3410 device ”). Select the “Install the software automatically” option and click on “Next” in Figure 6.



Figure 6 - Found New Hardware (“TUSB3410 Device”)

Once again, choose “Continue Anyway” to install the drivers.



Figure 7 -Hardware Installation Warning (“TUSB3410 Device”)

Click on “Finish” to complete the installation of the device as shown in Figure 8 below



Figure 8 - Device installation complete.

STEP 3: Windows displays the Found New Hardware dialog box (USB - Serial Port). Select the "Install the software automatically" option and click on "Next" in Figure 9



Figure 9-Found New Hardware (USB – Serial Port)

Once again, choose “Continue Anyway” to install the drivers.



Figure 10-Hardware Installation Warning (USB -Serial Port)

Click on “Finish” to complete the installation of the USB - Serial port device as shown in Figure 11 below



Figure 11 - USB -Serial port installation complete

The device manager display for a successful installation is shown in the Figure 12 below. Choose My Computer > Properties > Hardware > Device Manager to see this.




Figure 12 - Windows 2K Device Manager

To check the driver version, double click the "TUSB3410 Device" and select the driver tab as shown in Figure 13




Figure 13 - Device Driver Properties

TUSB3410/5052 Virtual COM Port Driver Uninstallation

OS: Windows 2000

STEP 1. To uninstall the driver s, run setup.exe located at directory \DISK1 of the installationmedia. Note that when setup.exe is run for the first time, it preinstalls the drivers. Running setup.exe asecond time uninstalls all the driver files and cleans up the registry entries that were added during installation.

The uninstaller displays the dialog box shown in Figure 18 below. Select “OK” to uninstall drivers.




Figure 18 - Confirm uninstall

To continue uninstallation, un - plug the device.




Figure 19 - Driver uninstallation

Once the device is unplugged the uninstaller proceeds to clean up all the files added during installation and the registry entries added during installation.

Click “Finish” to complete uninstallation.




Figure 20 - Uninstallation Complete.